

SDMS US EPA Region V

Imagery Insert Form

Document ID:

171833

Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:



Illegible due to bad source documents. Image(s) in SDMS is equivalent to hard copy.

Specify Type of Document(s) / Comments:



Includes X COLOR or X RESOLUTION variations.

Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible than the images. The original document is available for viewing at the Superfund Records Center.

Specify Type of Document(s) / Comments:

Colored Photographs



Confidential Business Information (CBI).

This document contains highly sensitive information. Due to confidentiality, materials with such information are not available in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document.

Specify Type of Document(s) / Comments:



Unscannable Material:

Oversized ___ or ___ Format.

Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center.

Specify Type of Document(s) / Comments:



Document is available at the Records Center .

Specify Type of Document(s) / Comments:



Roy F. Weston, Inc.
Suite 500
750 East Bunker Court
Vernon Hills, IL 60061-1450
847-918-4000 • Fax 847-918-4055
www.rfweston.com

1-718-333
29 March 2002

Mr. Steve Faryan
On Scene Coordinator
U.S. Environmental Protection Agency
77 West Jackson Boulevard
Chicago, Illinois 60604

TDD No.: S05-0111-010

Subject: Downers Grove Groundwater Investigation
Photo Log

Dear Mr. Faryan:

Roy F. Weston, Inc. (WESTON®) is pleased to submit a copy of the photo log for the Downers Grove site in Downers Grove, Illinois.

Should you have any questions or require additional information, please feel free to contact us at 847.918.4051.

Very truly yours,

ROY F. WESTON, INC


Omprakash Patel
Project Manager





DATE: 2/13/02

DESCRIPTION: View of CPT truck drilling at location CPT-62.




DATE: 2/13/02

DESCRIPTION: View of CPT contractor preparing rods for drilling at location CPT-62.




DATE: 2/13/02

DESCRIPTION: View of CPT contractor drilling through concrete at location CPT-62.




DATE: 2/14/02

DESCRIPTION: View of CPT truck drilling at location CPT-75 (Dynagear property).



DATE: 2/15/02

DESCRIPTION: View of CPT truck drilling at location CPT-51.



DATE: 2/15/02

DESCRIPTION: View of CPT truck drilling at location CPT-62.



DATE: 2/15/02

DESCRIPTION: View of CPT truck drilling at location CPT-56.



DATE: 2/18/02

DESCRIPTION: View of CPT truck drilling at location CPT-52.




DATE: 2/19/02

DESCRIPTION: View of CPT truck drilling at location CPT-52.



DATE: 2/26/02

DESCRIPTION: View of CPT truck drilling at location CPT-46 (Metra Parking Lot).



DATE: 2/26/02

DESCRIPTION: View of CPT truck drilling at location CPT-46 (Metra Parking Lot).



DATE: 2/26/02

DESCRIPTION: View of START B. Schaefer and drilling contractor collecting groundwater sample at location CPT-46 (Metra Parking Lot).




DATE: 2/27/02

DESCRIPTION: View CPT truck drilling at location CPT-45 (Belmont Ave).




DATE: 2/27/02

DESCRIPTION: View of road signs and CPT truck at location CPT-43 (Belmont Ave).



DATE: 2/28/02

DESCRIPTION: View of CPT truck drilling at location CPT-81 (Morey Property).



DATE: 3/1/02

DESCRIPTION: View of CPT truck drilling at location CPT-71.